







Order of PPE When Entering and Leaving the Laboratory

Donning/Entering		Doffing/Leaving	
	1. Lab Coat or Gown		1. Gloves <ul style="list-style-type: none">- Discard- Perform hand hygiene
	2. Mask		2. Lab Coat or Gown
	3. Safety Glasses		3. Safety Glasses
	4. Gloves <ul style="list-style-type: none">- Extend gloves to cover elastic cuff of lab coat/gown		4. Mask
			5. Wash hands <ul style="list-style-type: none">- Immediately after removing PPE